



INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**10196-36-5375**  
State Number  
**2153**

EQUIPMENT INSPECTED

State Number: <b>2153</b>	Type of Unit: Freight	Floor to Floor: 1 to 3
Capacity: 4000	Manuf: MONARCH	Speed: 60
Landings: 3	Installed: 07/22/1953	Rope Size:
Volts: 550	Complied: 07/22/1953	Entrances: 2
OWNER	OCCUPANT	
INTERNATIONAL TEXTILE GROUP, INC.	BURLINGTON FINISHING	
906 ANTHONY ST	906 ANTHONY ST	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 07/15/2010	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

- 8.6.1.6.2 All excess lubricant shall be cleaned from the equipment. Containers used to catch leakage shall not be allowed to overflow.
- 8.6.4.7.1 Clean the elevator pit.
- 2.12.6.1 Replace or repair the damaged pull chain hoistway access boxes.
- 2.2.5.1 Put the pit lights in proper working order.
- 2.11.12.8 Provide the missing pull straps.

Items must be corrected by: 08/14/2010

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: office

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

INTERNATIONAL TEXTILE GROUP, INC.  
906 ANTHONY ST  
BURLINGTON, NC, 27215