

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17275-76-3171 State Number H1925

5

State Number: H1925 Type of Unit: Hand Lift Floor to Floor: 1 to 2 Capacity: 750 Manuf: NATL W-O-V Speed: 9 Landings: 2 Installed: 09/12/2007 Rope Size: Volts: 115 Complied: 09/12/2007 Entrances: 2 OWNER OCCUPANT W JEFFERSON UNITED METHODIST CH W JEFFERSON UNITED METHODIST CH 107 W 2ND STREET WEST JEFFERSON, NC, 28694 WEST JEFFERSON, NC, 28694 INSPECTION INFORMATION Inspection Date Type Inspection Certificate Status Inspector 76 - Crank VIOLATIONS Place the in-car emergency lights in working order. The auxillary lighting illumination shall not be less than 2 lx (0.2 fc) to between 48 in. and 35 in. above the car floor and approximately 12 in. centered horizontally in front o 8.6.4.13.1 Place the hoistway door unlocking devices (interlocks) in proper working order.					
Capacity: 750 Manuf: NATL W-O-V Speed: 9 Landings: 2 Installed: 09/12/2007 Rope Size: Volts: 115 Complied: 09/12/2007 Entrances: 2 OWNER OCCUPANT W JEFFERSON UNITED METHODIST CH W JEFFERSON UNITED METHODIST CH 107 W 2ND STREET 107 W 2ND STREET WEST JEFFERSON, NC, 28694 WEST JEFFERSON, NC, 28694 INSPECTION INFORMATION Inspection Date Type Inspection Certificate Status Re-issued 76 - Crank VIOLATIONS Place the in-car emergency lights in working order. The auxillary lighting illumination shall not be less than 2 lx (0.2 fc) to between 48 in. and 35 in. above the car floor and approximately 12 in. centered horizontally in front o					
Landings: 2 Installed: 09/12/2007 Rope Size: Volts: 115 Complied: 09/12/2007 Entrances: 2 OWNER OCCUPANT W JEFFERSON UNITED METHODIST CH 107 W 2ND STREET WEST JEFFERSON, NC, 28694 INSPECTION INFORMATION Inspection Date 10/02/2017 Type Inspection Routine Re-issued T6 - Crank VIOLATIONS Place the in-car emergency lights in working order. The auxillary lighting illumination shall not be less than 2 lx (0.2 fc) to between 48 in. and 35 in. above the car floor and approximately 12 in. centered horizontally in front o 8.6.4.13.1 Place the hoistway door unlocking devices (interlocks) in proper working order.			ift		
Volts: 115 Complied: 09/12/2007 Entrances: 2 OWNER OCCUPANT W JEFFERSON UNITED METHODIST CH W JEFFERSON UNITED METHODIST CH 107 W 2ND STREET 107 W 2ND STREET WEST JEFFERSON, NC, 28694 WEST JEFFERSON, NC, 28694 INSPECTION INFORMATION Inspection Date 10/02/2017 Type Inspection Routine Re-issued 76 - Crank VIOLATIONS Place the in-car emergency lights in working order. The auxillary lighting illumination shall not be less than 2 lx (0.2 fc) to between 48 in. and 35 in. above the car floor and approximately 12 in. centered horizontally in front o 3.6.4.13.1 Place the hoistway door unlocking devices (interlocks) in proper working order.	Capacity: 750 Manuf: NATL W-O		V	Speed: 9	
OWNER W JEFFERSON UNITED METHODIST CH W JEFFERSON UNITED METHODIST CH 107 W 2ND STREET WEST JEFFERSON, NC, 28694 WEST JEFFERSON, NC, 28694 INSPECTION INFORMATION Inspection Date 10/02/2017 Type Inspection Routine Certificate Status Re-issued 76 - Crank VIOLATIONS Place the in-car emergency lights in working order. The auxillary lighting illumination shall not be less than 2 lx (0.2 fc) to between 48 in. and 35 in. above the car floor and approximately 12 in. centered horizontally in front o	2	Installed: 09/12/2007		Rope Size:	
W JEFFERSON UNITED METHODIST CH 107 W 2ND STREET WEST JEFFERSON, NC, 28694 INSPECTION INFORMATION Inspection Date 10/02/2017 Routine Type Inspection Re-issued VIOLATIONS Place the in-car emergency lights in working order. The auxillary lighting illumination shall not be less than 2 lx (0.2 fc) a between 48 in. and 35 in. above the car floor and approximately 12 in. centered horizontally in front o 6.4.13.1 Place the hoistway door unlocking devices (interlocks) in proper working order.	Volts: 115 Complied:		7	Entrances: 2	
107 W 2ND STREET WEST JEFFERSON, NC, 28694 INSPECTION INFORMATION Inspection Date 10/02/2017 Type Inspection Routine VIOLATIONS Place the in-car emergency lights in working order. The auxillary lighting illumination shall not be less than 2 lx (0.2 fc) to between 48 in. and 35 in. above the car floor and approximately 12 in. centered horizontally in front o 6.4.13.1 Place the hoistway door unlocking devices (interlocks) in proper working order.			OCCUPANT		
Inspection Date Type Inspection Certificate Status Inspector 10/02/2017 Routine Re-issued 76 - Crank VIOLATIONS Place the in-car emergency lights in working order. The auxillary lighting illumination shall not be less than 2 lx (0.2 fc) restricted to the hoistway door unlocking devices (interlocks) in proper working order.	W JEFFERSON UNITED METHODIST CH		W JEFFERSON UNITED METHODIST CH		
INSPECTION INFORMATION Inspection Date Type Inspection Certificate Status Inspector 76 - Crank VIOLATIONS Place the in-car emergency lights in working order. The auxillary lighting illumination shall not be less than 2 lx (0.2 fc) restricted between 48 in. and 35 in. above the car floor and approximately 12 in. centered horizontally in front o 6.4.13.1 Place the hoistway door unlocking devices (interlocks) in proper working order.	107 W 2ND STREET		107 W 2ND STREET		
Inspection Date Type Inspection Certificate Status Inspector 10/02/2017 Routine Re-issued 76 - Crank VIOLATIONS Place the in-car emergency lights in working order. The auxillary lighting illumination shall not be less than 2 lx (0.2 fc) restricted between 48 in. and 35 in. above the car floor and approximately 12 in. centered horizontally in front on 6.4.13.1 Place the hoistway door unlocking devices (interlocks) in proper working order.	FFERSON, NC, 28694		WEST JEFFERSON, NC, 28694		
Inspection Date 10/02/2017 Type Inspection Re-issued Type Inspector 76 - Crank VIOLATIONS Place the in-car emergency lights in working order. The auxillary lighting illumination shall not be less than 2 lx (0.2 fc) to between 48 in. and 35 in. above the car floor and approximately 12 in. centered horizontally in front o 6.4.13.1 Place the hoistway door unlocking devices (interlocks) in proper working order.		INSPECT			
Place the in-car emergency lights in working order. The auxillary lighting illumination shall not be less than 2 lx (0.2 fc) r between 48 in. and 35 in. above the car floor and approximately 12 in. centered horizontally in front o 6.4.13.1 Place the hoistway door unlocking devices (interlocks) in proper working order.					County ASHE
between 48 in. and 35 in. above the car floor and approximately 12 in. centered horizontally in front o 6.4.13.1 Place the hoistway door unlocking devices (interlocks) in proper working order.					
Place the hoistway door unlocking devices (interlocks) in proper working order.	Place the in-car emerge between 48 in. and 35 i	ncy lights in working order. The auxilla	ary lighting illumination shall not y 12 in. centered horizontally in fi	be less than 2 lx (0.2 fc) measuront o	ured at any poi
	Place the hoistway door	r unlocking devices (interlocks) in prop	er working order.		
.25.3 Place the final limit switch / device in working order.	Place the final limit swi	tch / device in working order.			
.7.3.1 Provide clear access to the elevator	Provide clear access to	the elevator			
e) 2.25.3 2.7.3.1	7 2 R	Place the in-car emerge between 48 in. and 35 i	per: H1925 Type of Unit: Hand L 750 Manuf: NATL W-O- Installed: 09/12/2007 Complied: 09/12/200 RSON UNITED METHODIST CH D STREET FFERSON, NC, 28694 INSPECT Type Inspection Routine V Place the in-car emergency lights in working order. The auxilla between 48 in. and 35 in. above the car floor and approximatel Place the hoistway door unlocking devices (interlocks) in prop Place the final limit switch / device in working order.	ber: H1925 Type of Unit: Hand Lift Manuf: NATL W-O-V Installed: 09/12/2007 Complied: 09/12/2007 Complied: 09/12/2007 OCCUPANT RSON UNITED METHODIST CH D STREET TOT W 2ND STREET FERSON, NC, 28694 INSPECTION INFORMATION INSPECTION INFORMATION INSPECTION INFORMATION Place the in-car emergency lights in working order. The auxillary lighting illumination shall not between 48 in. and 35 in. above the car floor and approximately 12 in. centered horizontally in fillumination order. Place the hoistway door unlocking devices (interlocks) in proper working order. Place the final limit switch / device in working order.	rer: H1925 Type of Unit: Hand Lift Floor to Floor: 1 to 2 250 Manuf: NATL W-O-V Speed: 9 2 Installed: 09/12/2007 Rope Size:

Items must be corrected by: 12/01/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: Frances herzog 336-246-592 Inspector _____

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

W JEFFERSON UNITED METHODIST CH
An invoice will be mailed to: 107 W 2ND STREET

WEST JEFFERSON, NC, 28694