



INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
12081-52-2661
State Number
13317

EQUIPMENT INSPECTED

State Number: 13317	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: SOUTHERN	Speed: 100
Landings: 2	Installed: 08/23/1989	Rope Size: 0
Volts: 208	Complied: 08/23/1989	Entrances: 1
OWNER	OCCUPANT	
GRANDFATHER COUNTRY CLUB	GRANDFATHER COUNTRY CLUB	
2120 HWY.105 NORTH	1225 HWY.105 NORTH	
LINVILLE, NC, 28646	LINVILLE, NC, 28646	

INSPECTION INFORMATION

Inspection Date 03/21/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 52 - Sosebee	County AVERY	6
-------------------------------	----------------------------	---------------------------------	---------------------------	-----------------	---

VIOLATIONS

- 8.11.3.2.1 Perform the annual relief valve test and provide proper tag.
- 8.6.4.13.1[k] Properly maintain door closers, where required. (Top floor hoistway door will not shut own its own.)
- 2.9.1 Assign identification (numbers or letters) to the equipment where required.

Items must be corrected by: 04/20/2012

Elevator Name: # 1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Grandfather Country Club 828-896-4531

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

GRANDFATHER COUNTRY CLUB
2120 HWY.105 NORTH
LINVILLE, NC, 28646