



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)

Invoice Number  
**551236**

### EQUIPMENT INSPECTED

State Number: 20246	Type of Unit: Passenger	Landings: 4	Manuf: THYSSEN KRUPP
Capacity: 5000	Installed: 03/14/2002	Complied: 03/14/2002	Speed: 150
Volts: 480	Floor to Floor: 1 to 4	Entrances: 1	Rope Size:
Owner: RANDOLPH COUNTY, 1125 MCDOWELL RD, ASHEBORO, NC, 27203			
Occupant: RANDOLPH COUNTY COURT HOUSE, 139 N COX SR, ASHEBORO, NC, 27203			

### INSPECTION INFORMATION

Inspection Date 07/17/2008	Type Inspection Routine	Certificate Status Re-issued	Inspector 12 - Essick	County Name RANDOLPH	County Code 76
-------------------------------	----------------------------	---------------------------------	--------------------------	-------------------------	-------------------

### VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Maintenance

Inspector \_\_\_\_\_

### INVOICE

No other invoice will be issued.  
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,  
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: RANDOLPH COUNTY, 1125 MCDOWELL RD, ASHEBORO, NC, 27203  
Occupant: RANDOLPH COUNTY COURT HOUSE, 139 N COX SR, ASHEBORO, NC, 27203

Invoice Number  
**551236**  
State Nbr: 20246  
Date: 07/17/2008  
Fee: \$175