



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
556959

EQUIPMENT INSPECTED

State Number: H1969	Type of Unit: Hand Lift	Landings: 2	Manuf: TKE
Capacity: 750	Installed: 04/23/2008	Complied: 04/23/2008	Speed: 12
Volts: 120	Floor to Floor: 1 to 2	Entrances: 2	Rope Size: 0
Owner: SECOND BAPTIST CHURCH, 2516 HWY 264 WEST, WASHINGTON, NC, 27889			
Occupant: SECOND BAPTIST CHURCH, 2516 HWY 264 WEST, WASHINGTON, NC, 27889			

INSPECTION INFORMATION

Inspection Date 04/23/2008	Type Inspection New	Certificate Status Issued	Inspector 16 - Moore	County Name BEAUFORT	County Code 7
-------------------------------	------------------------	------------------------------	-------------------------	-------------------------	------------------

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

n/a No violations found

Violations pointed out to: Wayne with Outer Banks Elevator

Inspector _____

INVOICE

No other invoice will be issued.
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: SECOND BAPTIST CHURCH, 2516 HWY 264 WEST, WASHINGTON, NC, 27889
Occupant: SECOND BAPTIST CHURCH, 2516 HWY 264 WEST, WASHINGTON, NC, 27889

Invoice Number
556959

State Nbr: H1969
Date: 04/23/2008
Fee: \$200