



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
557150

EQUIPMENT INSPECTED

State Number: N7.19	Type of Unit: Freight	Landings: 2	Manuf: WESTBROOK
Capacity: 2000	Installed: 08/29/1979	Complied: 08/29/1979	Speed: 50
Volts: 220	Floor to Floor: 1 to 2	Entrances: 2	Rope Size: 5/8
Owner: MAOLA ICE CREAM COMPANY, PO BOX 759, WASHINGTON, NC, 27889			
Occupant: UNOCCUPIED BUILDING, 115 EAST WATER ST, WASHINGTON, NC, 27889			

INSPECTION INFORMATION

Inspection Date 07/29/2008	Type Inspection Routine	Certificate Status Re-issued	Inspector 16 - Moore	County Name BEAUFORT	County Code 7
-------------------------------	----------------------------	---------------------------------	-------------------------	-------------------------	------------------

Violation Abatement Date: 08/28/2008

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

8.11.2.2.2 Perform an annual no load safety test and provide proper tags.

Violations pointed out to: Mayor of water st.

Inspector _____

INVOICE

No other invoice will be issued.
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: MAOLA ICE CREAM COMPANY, PO BOX 759, WASHINGTON, NC, 27889
Occupant: UNOCCUPIED BUILDING, 115 EAST WATER ST, WASHINGTON, NC, 27889

Invoice Number
557150
State Nbr: N7.19
Date: 07/29/2008
Fee: \$200