



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
557294

EQUIPMENT INSPECTED

State Number: 6858 Type of Unit: Passenger Landings: 3 Manuf: WESTBROOK
Capacity: 2000 Installed: 06/15/1972 Complied: 10/25/1993 Speed: 100
Volts: 220 Floor to Floor: B to 2 Entrances: 1 Rope Size: 0
Owner: BEAUFORT CO COURTHOUSE, PO BOX 1027, WASHINGTON, NC, 27889
Occupant: BEAUFORT CO COURT HOUSE, 112 W SECOND ST, WASHINGTON, NC, 27889

INSPECTION INFORMATION

Inspection Date 10/17/2008	Type Inspection Routine	Certificate Status Re-issued	Inspector 16 - Moore	County Name BEAUFORT	County Code 7
-------------------------------	----------------------------	---------------------------------	-------------------------	-------------------------	------------------

Violation Abatement Date: 11/16/2008

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

8.6.1.6.5 Provide a class "ABC" fire extinguisher in the machine room or control space convenient to the access door.

Violations pointed out to: Annette in Maintenance

Inspector _____

INVOICE

No other invoice will be issued.
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: BEAUFORT CO COURTHOUSE, PO BOX 1027, WASHINGTON, NC, 27889
Occupant: BEAUFORT CO COURT HOUSE, 112 W SECOND ST, WASHINGTON, NC, 27889

Invoice Number
557294

State Nbr: 6858
Date: 10/17/2008
Fee: \$175