



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
557295

EQUIPMENT INSPECTED

State Number: 6859 Type of Unit: Passenger Landings: 3 Manuf: WESTBROOK
Capacity: 1300 Installed: 06/15/1972 Complied: 07/25/1972 Speed: 100
Volts: 220 Floor to Floor: 1 to 2 Entrances: 1 Rope Size: 0
Owner: BEAUFORT CO COURTHOUSE, PO BOX 1027, WASHINGTON, NC, 27889
Occupant: BEAUFORT CO COURT HOUSE, 112 W SECOND ST, WASHINGTON, NC, 27889

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County Name	County Code
10/17/2008	Routine	Re-issued	16 - Moore	BEAUFORT	7

Violation Abatement Date: 11/16/2008

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

2.2.5 Repair pit light to work
2.7.9.1 Repair machine room light to work

Violations pointed out to: Annette in Maintenance

Inspector _____

INVOICE

No other invoice will be issued.
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: BEAUFORT CO COURTHOUSE, PO BOX 1027, WASHINGTON, NC, 27889
Occupant: BEAUFORT CO COURT HOUSE, 112 W SECOND ST, WASHINGTON, NC, 27889

Invoice Number
557295
State Nbr: 6859
Date: 10/17/2008
Fee: \$175