



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
557455

EQUIPMENT INSPECTED

State Number: 14964 Type of Unit: Passenger Landings: 2 Manuf: US ELEVATOR
Capacity: 2500 Installed: 04/02/1993 Complied: 04/02/1993 Speed: 100
Volts: 480 Floor to Floor: 1 to 2 Entrances: 1 Rope Size: 0
Owner: BEAUFORT COUNTY, P O BOX 1069, WASHINGTON, NC, 27889
Occupant: BEAUFORT COMMUNITY COLLEGE, 5337 HWY 264 EAST, WASHINGTON, NC, 27889

INSPECTION INFORMATION

| Inspection Date | Type Inspection | Certificate Status | Inspector | County Name | County Code |
|-----------------|-----------------|--------------------|------------|-------------|-------------|
| 02/05/2009 | Routine | Re-issued | 16 - Moore | BEAUFORT | 7 |

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

n/a No violations found

Violations pointed out to: Melvin Lodge

Inspector _____

INVOICE

No other invoice will be issued.

If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: BEAUFORT COUNTY, P O BOX 1069, WASHINGTON, NC, 27889
Occupant: BEAUFORT COMMUNITY COLLEGE, 5337 HWY 264 EAST, WASHINGTON, NC,
27889

Invoice Number
557455

State Nbr: 14964
Date: 02/05/2009
Fee: \$175