



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)

Invoice Number  
**557456**

### EQUIPMENT INSPECTED

State Number: 6917      Type of Unit: Dumbwaiter      Landings: 2      Manuf: MATOT  
Capacity: 300      Installed: 01/28/1971      Complied: 01/28/1971      Speed: 50  
Volts: 270      Floor to Floor: 1 to 2      Entrances: 1      Rope Size: 1/4  
Owner: BEAUFORT COUNTY, PO BOX 1069, WASHINGTON, NC, 27889  
Occupant: BEAUFORT CO COMMUNITY COLLEGE, 5337 HWY 264 EAST, WASHINGTON, NC, 27889

### INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County Name	County Code
02/05/2009	Routine	Re-issued	16 - Moore	BEAUFORT	7

### VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

n/a      No violations found

Violations pointed out to: Melvin Lodge

Inspector \_\_\_\_\_

### INVOICE

No other invoice will be issued.

If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,  
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: BEAUFORT COUNTY, PO BOX 1069, WASHINGTON, NC, 27889  
Occupant: BEAUFORT CO COMMUNITY COLLEGE, 5337 HWY 264 EAST, WASHINGTON,  
NC, 27889

Invoice Number  
**557456**

State Nbr: 6917  
Date: 02/05/2009  
Fee: \$65