



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
559253

EQUIPMENT INSPECTED

State Number: 17595 Type of Unit: Passenger Landings: 2 Manuf: THYSSEN KRUPP
Capacity: 2100 Installed: 07/10/1998 Complied: 07/16/1998 Speed: 95
Volts: 480 Floor to Floor: 1 to 2 Entrances: 1 Rope Size:
Owner: SOUTH PIEDMONT COMMUNITY COLLEGE, PO BOX 126, POLKTON, NC, 28135
Occupant: SOUTH PIEDMONT COMMUNITY COLLEGE, 129 LEDBETTER ST, POLKTON, NC, 28135

Elevator Name: MARTIN BLDG

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County Name	County Code
06/12/2008	Routine	Re-issued	8 - Burris	ANSON	4

Violation Abatement Date: 07/12/2008

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

- 8.6 RESTORE OPERATION OF AUTO LOWERING DEVICE
- 8.11 PERFORM ANNUAL PRESSURE RELIEF VALVE TEST

Violations pointed out to: REP- AL ODOM

Inspector _____

INVOICE

No other invoice will be issued.

If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: SOUTH PIEDMONT COMMUNITY COLLEGE, PO BOX 126, POLKTON, NC, 28135
Occupant: SOUTH PIEDMONT COMMUNITY COLLEGE, 129 LEDBETTER ST, POLKTON,
NC, 28135

Invoice Number
559253

State Nbr: 17595
Date: 06/12/2008
Fee: \$175