



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)

Invoice Number  
**559263**

### EQUIPMENT INSPECTED

State Number: 10528      Type of Unit: Passenger      Landings: 2      Manuf: THYSSEN KRUPP  
Capacity: 2500      Installed: 05/24/1983      Complied: 05/24/1983      Speed: 100  
Volts: 208      Floor to Floor: 1 to 2      Entrances: 1      Rope Size:  
Owner: ANSON CO ADMIN BLDG, 101 S.GREENE ST, WADESBORO, NC, 28170  
Occupant: ANSON CO COURTHOUSE, 114 N GREEN ST (ROOM 30), WADESBORO, NC, 28170

Elevator Name: VISITOR ELEVATOR

### INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County Name	County Code
06/17/2008	Routine	Re-issued	8 - Burris	ANSON	4

Violation Abatement Date: 07/17/2008

### VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

8.6      NONE

Violations pointed out to: REP- BONNIE HUNTLEY (CO MGR OFFICE)

Inspector \_\_\_\_\_

### INVOICE

No other invoice will be issued.

If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,  
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: ANSON CO ADMIN BLDG, 101 S.GREENE ST, WADESBORO, NC, 28170  
Occupant: ANSON CO COURTHOUSE, 114 N GREEN ST (ROOM 30), WADESBORO, NC, 28170

Invoice Number  
**559263**

State Nbr: 10528  
Date: 06/17/2008  
Fee: \$175