



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
559268

EQUIPMENT INSPECTED

State Number: 8196 Type of Unit: Passenger Landings: 3 Manuf: OTIS
Capacity: 4000 Installed: 03/11/1975 Complied: 04/02/1975 Speed: 100
Volts: 480 Floor to Floor: 1 to 3 Entrances: 1 Rope Size: 5/8
Owner: ANSON COMM COLLEGE, HWY 74 / PO BOX 126, POLKTON, NC, 28138
Occupant: ANSON COMM COLLEGE, 514 N WASHINGTON ST, WADESBORO, NC, 28170

INSPECTION INFORMATION

Inspection Date 06/17/2008	Type Inspection Properly Landed	Certificate Status Not Issued	Inspector 8 - Burris	County Name ANSON	County Code 4
-------------------------------	------------------------------------	----------------------------------	-------------------------	----------------------	------------------

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

NCAC

PROPERLY LANDED

Violations pointed out to: REP-

Inspector _____

INVOICE

No other invoice will be issued.
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: ANSON COMM COLLEGE, HWY 74 / PO BOX 126, POLKTON, NC, 28138
Occupant: ANSON COMM COLLEGE, 514 N WASHINGTON ST, WADESBORO, NC, 28170

Invoice Number
559268

State Nbr: 8196
Date: 06/17/2008
Fee: \$0