

28170

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm

Invoice Number 559272

EQUIPMENT INSPECTED						
State Number: H832 Capacity: 750 Volts: 110 Owner: FIRST PRESBYTER Occupant: FIRST PRESBYTI		8 Com o UL Entra GREEN STREET, WADES		Speed: Rope S	Manuf: RENAME Speed: 15 Rope Size: 1/4	
		ON INFORMATION				
Inspection Date 06/18/2008	Type Inspection Not Inspected		Inspector 8 - Burris	County Name ANSON	County Cod	
Violation Abatement Date:		VIOLATIONS FOUND				
Notify the Elevator Bureau in v equipment into compliance with	h current codes.	ations Form when the follo				
A18.1						
Violations pointed out to: REP- NO ONE AT BLDO		Inspe		spector	ector	
		INVOICE				
	No other invoice will					
If not paid within 30 Return this stub with payment 1101 Mail Service Center, Ral	to: NC Department of La	e, your certificate become abor, Budget and Purchasin		55	ce Number	
Owner: FIRST PRESBYTER 28170	IAN CHURCH, 208 S. C	GREEN STREET, WADE	SBORO, NC,	State Nbr: Date: Fee:	H832 06/18/2008 \$0	

Occupant: FIRST PRESBYTERIAN CHURCH, 208 S. GREEN STREET, WADESBORO, NC,