

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm

Invoice Number 559274

		EQUIPMENT INSPECT	ΈD			
State Number: 11471 Type of Unit: Passe Capacity: 2100 Installed: 11/15/198 Volts: 208 Floor to Floor: G to Owner: FIRST BAPTIST CHURCH, P.O.BOX 423 Occupant: FIRST BAPTIST CHURCH, 309 LEE A		5 Complied: 11/25/1985 3 Entrances: 1 WADESBORO, NC, 28170 VE, WADESBORO, NC, 28170		Manuf: THYSSEN Speed: 125 Rope Size:	•	
Elevator Name: PASSENGER	ELEV INSPECT	TION INFORMATION				
Inspection Date 06/19/2008	Type Inspection Routine	Certificate Status Re-issued	Inspector 8 - Burris	County Name ANSON	County Coo	
Violation Abatement D	Pate: 07/19/2008	VIOLATIONS FOUND				
Notify the Elevator Bureau equipment into compliance		lations Form when the follow	wing corrections	have been made in orde	r to bring your	
8.6	NONE					
Violations pointed out to: 1	REP- DENNISE WHITLEY		I	nspector		
		INVOICE				
If not paid within	No other invoice wil a 30 days from date of invoice	l be issued. ce, your certificate becomes	invalid.	Invoice	e Number	
Return this stub with paym 1101 Mail Service Center,		abor, Budget and Purchasing	g Division,	559 State Nbr:	9274 11471 06/19/2008	
Owner: FIRST BAPTIST CHURCH, P.O.BOX 423, WADESBORO, NC, 28170					\$175	

Occupant: FIRST BAPTIST CHURCH, 309 LEE AVE, WADESBORO, NC, 28170