



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
559279

EQUIPMENT INSPECTED

State Number: 8027	Type of Unit: Freight	Landings: 3	Manuf: PARK
Capacity: 6000	Installed: 06/04/1974	Complied: 09/17/2003	Speed: 100
Volts: 220	Floor to Floor: 1 to 3	Entrances: 2	Rope Size:
Owner: WADE MANUFACTURING CO, P.O.BOX 32, WADESBORO, NC, 28170			
Occupant: WADE MANUFACTURING CO, HIGHWAY 74 EAST, WADESBORO, NC, 28170			

INSPECTION INFORMATION

Inspection Date 06/19/2008	Type Inspection Routine	Certificate Status Re-issued	Inspector 8 - Burris	County Name ANSON	County Code 4
-------------------------------	----------------------------	---------------------------------	-------------------------	----------------------	------------------

Violation Abatement Date: 07/19/2008

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

8.6 REPLACE MISSING PLUGGING ROD TOP LANDING & AJUST GAP IN DOOR & COUNTER BALANCE DOORS
8.6 COUNTER BALANCE REAR GATE

Violations pointed out to: REP- KENNETH GREENE

Inspector _____

INVOICE

No other invoice will be issued.
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: WADE MANUFACTURING CO, P.O.BOX 32, WADESBORO, NC, 28170
Occupant: WADE MANUFACTURING CO, HIGHWAY 74 EAST, WADESBORO, NC, 28170

Invoice Number
559279

State Nbr: 8027
Date: 06/19/2008
Fee: \$175