



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
559446

EQUIPMENT INSPECTED

State Number: 8870	Type of Unit: Passenger	Landings: 3	Manuf: THYSSEN KRUPP
Capacity: 300	Installed: 08/23/1979	Complied: 08/23/1979	Speed: 100
Volts:	Floor to Floor: to	Entrances:	Rope Size: 1/2
Owner: CARGILL NUTRENA FEED DIVISON, P O BOX 1185, NORWOOD, NC, 28128			
Occupant: NUTRENA FEEDS, HWY 52 ROUTE 2 BOX 362, WADESBORO, NC, 28170			

INSPECTION INFORMATION

Inspection Date 08/21/2008	Type Inspection Condemned	Certificate Status Not Issued	Inspector 8 - Burris	County Name ANSON	County Code 4
-------------------------------	------------------------------	----------------------------------	-------------------------	----------------------	------------------

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: REP- NO ACCESS

Inspector _____

INVOICE

No other invoice will be issued.
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: CARGILL NUTRENA FEED DIVISON, P O BOX 1185, NORWOOD, NC, 28128
Occupant: NUTRENA FEEDS, HWY 52 ROUTE 2 BOX 362, WADESBORO, NC, 28170

Invoice Number
559446

State Nbr: 8870
Date: 08/21/2008
Fee: \$0