



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
559788

EQUIPMENT INSPECTED

State Number: H2078 Type of Unit: Hand Lift Landings: 2 Manuf: SAVARIA
Capacity: 750 Installed: 03/04/2009 Complied: 03/04/2009 Speed: 8
Volts: 120 Floor to Floor: 1 to 1 Entrances: 2 Rope Size:
Owner: ANSON COUNTY GOVERNMENT, 114 N GREENE STREET, WADESBORO, NC, 28170
Occupant: ANSON COUNTY ADMIN OFB, 101 S GREENE STREET, WADESBORO, NC, 28170

Elevator Name: 1ST FLOOR LIFT

INSPECTION INFORMATION

Inspection Date 03/04/2009	Type Inspection New	Certificate Status Issued	Inspector 8 - Burris	County Name ANSON	County Code 4
-------------------------------	------------------------	------------------------------	-------------------------	----------------------	------------------

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: REP- CHUCK H. (ETS ELEVATOR CO)

Inspector _____

INVOICE

No other invoice will be issued.

If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: ANSON COUNTY GOVERNMENT, 114 N GREENE STREET, WADESBORO, NC,
28170
Occupant: ANSON COUNTY ADMIN OFB, 101 S GREENE STREET, WADESBORO, NC,
28170

Invoice Number
559788

State Nbr: H2078
Date: 03/04/2009
Fee: \$65