



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)

Invoice Number  
**566876**

### EQUIPMENT INSPECTED

State Number: 22472      Type of Unit: Passenger      Landings: 4      Manuf: THYSSEN KRUPP  
Capacity: 3000      Installed: 07/20/2004      Complied: 07/20/2004      Speed: 125  
Volts: 208      Floor to Floor: 1 to 4      Entrances: 1      Rope Size: .  
Owner: CAMS, 3960 EXECUTIVE PARK BLVD. SUITE 8, SOUTHPORT, NC, 28461  
Occupant: ISLANDER RESORT #45, 1 VIA DOLOROSA, OCEAN ISLE, NC, 28469

### INSPECTION INFORMATION

Inspection Date 04/01/2008	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County Name BRUNSWICK	County Code 10
-------------------------------	----------------------------	---------------------------------	--------------------------	--------------------------	-------------------

### VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

n/a      No violations found

Violations pointed out to: UNAVAILABLE

Inspector \_\_\_\_\_

### INVOICE

No other invoice will be issued.  
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,  
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: CAMS, 3960 EXECUTIVE PARK BLVD. SUITE 8, SOUTHPORT, NC, 28461  
Occupant: ISLANDER RESORT #45, 1 VIA DOLOROSA, OCEAN ISLE, NC, 28469

Invoice Number  
**566876**  
State Nbr: 22472  
Date: 04/01/2008  
Fee: \$175