N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
566929

EQUIPMENT INSPECTED

State Number: 23516	Type of Unit: Passenger	Landings: 3	Manuf: OTIS
Capacity: 2100	Installed: 02/22/2006	Complied: 02/22/2006	Speed: 100
Volts: 208	Floor to Floor: 1 to 3	Entrances: 1	Rope Size: 0

Owner: COMMUNITY AASOCIATION MGMT., P.O. BOX 8126, 0CEAN ISLE BEACH, NC, 28469
Occupant: VILLAS ON OSPREY RIDGE, 174 CLUB HOUSE RD, SUNSET BEACH, NC, 28468

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County Name	County Code
05/05/2008	Routine	Re-issued	48 - Martin	BRUNSWICK	10

Violation Abatement Date: 06/04/2008 VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

8.6.4.7.4 Water and oil shall not be allowed to accumulate on pit floors. WATER IN PIT.

8.6.4.3.1 The lubrication of guide rails shall be in accordance with the requirements on the crosshead data plate where provided. LUB. GUIDE RAILS.

Violations pointed out to: UNAVAILABLE Inspector _____

INVOICE

No other invoice will be issued.
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: COMMUNITY AASOCIATION MGMT., P.O. BOX 8126, 0CEAN ISLE BEACH, NC, 28469
Occupant: VILLAS ON OSPREY RIDGE, 174 CLUB HOUSE RD, SUNSET BEACH, NC, 28468

Invoice Number
566929
State Nbr: 23516
Date: 05/05/2008
Fee: $175