



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
566956

EQUIPMENT INSPECTED

State Number: 20869	Type of Unit: Passenger	Landings: 4	Manuf: OTIS
Capacity: 2500	Installed: 02/04/2003	Complied: 02/04/2003	Speed: 100
Volts: 208	Floor to Floor: 1 to 4	Entrances: 1	Rope Size: 0
Owner: ELCO PROPERTIES, P.O. BOX 931, DAVIDSON, NC, 28036			
Occupant: 1769 HORBORAGE CONDO, 1769 HORBORAGE DRIVE, OCEAN ISLE, NC, 28469			

INSPECTION INFORMATION

Inspection Date 05/27/2008	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County Name BRUNSWICK	County Code 10
-------------------------------	----------------------------	---------------------------------	--------------------------	--------------------------	-------------------

Violation Abatement Date: 06/16/2008

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

- 8.1.1[c] Keys shall be kept on the premises in a location readily accessible to the personnel in the assigned group, but not where they are accessible to the general public. PROVIDE KEY'S FOR ACCESS.

Violations pointed out to: UNAVAILABLE

Inspector _____

INVOICE

No other invoice will be issued.
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: ELCO PROPERTIES, P.O. BOX 931, DAVIDSON, NC, 28036
Occupant: 1769 HORBORAGE CONDO, 1769 HORBORAGE DRIVE, OCEAN ISLE, NC, 28469

Invoice Number
566956
State Nbr: 20869
Date: 05/27/2008
Fee: \$175