

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm

Invoice	Number
566	5995

		EQUIPMENT I	NSPECTED			
State Number: H1672	5 1		Landings: 2		Manuf: GARAVENTA	
Capacity: 750		Installed: 11/01/2005 Complied: 11/01/2005		Speed: 0		
Volts: 240	Floor to Floor: 1		Entrances: 2	Rope Size:		
	CHURCH, PO BOX 176, IST CHURCH, 500 SOUT					
		INSPECTION IN				
Inspection Date 06/27/2008	Type Inspection Routine	Certificate Statu Re-issued	s Inspector 48 - Martin	County Name BLADEN	County Code 9	
		VIOLATIONS				
Notify the Elevator Bu	reau in writing on Correcte equi	ed Violations Form wl ipment into complianc		ons have been made in	order to bring you	
n/a No vi	olations found					
Violations pointed out to: KELLY				Inspector		
		INVO	ICE			
	No other inveice v	will be issued				
No other invoice will be issued. If not paid within 30 days from date of invoice, your certi			pecomes invalid.		N 1	
Return this stub with payment to: NC Department of Labor, Budget and Purchasing D 1101 Mail Service Center, Raleigh, NC 27699-1101			560 State Nbr:			
Owner: FIRST BAPTIST CHURCH, PO BOX 176, BLADENBORO, NC, 28320				Date: Fee:	06/27/2008 \$65	

Occupant: FIRST BAPTIST CHURCH, 500 SOUTH MAIN ST, BLADENBORO, NC, 28320