N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
567171

EQUIPMENT INSPECTED

State Number: 23453	Type of Unit: Passenger	Landings: 3	Manuf: OTIS
Capacity: 3000	Installed: 12/05/2005	Complied: 12/05/2005	Speed: 150
Volts: 208	Floor to Floor: 1 to 3	Entrances: 1	Rope Size: 0

Owner: CAW CAW DEV330 S MILLDLETON DR, 339 S MILLDLETON DR, CALABASH, NC, 28468

Occupant: COLONY II BLDG 8, 908 RESORT CIRCLE, SUNSET BEACH, NC, 28467

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County Name	County Code
11/07/2008	Routine	Re-issued	48 - Martin	BRUNSWICK	10

Violation Abatement Date: 11/17/2008 VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

8.6.4.15 Emergency operation of signaling devices,lighting, communication, and ventilation, shall be maintained.EMER. PHONE INOPERATIVE.

8.1.1[c] Keys shall be kept on the premises in a location readily accessible to the personnel in the assigned group, but not where they are accessible to the general public.

Violations pointed out to: UNAVAILABLE Inspector _____

INVOICE

No other invoice will be issued.
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division, 1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: CAW CAW DEV330 S MILLDLETON DR, 339 S MILLDLETON DR, CALABASH, NC, 28468
Occupant: COLONY II BLDG 8, 908 RESORT CIRCLE, SUNSET BEACH, NC, 28467

Invoice Number
567171
State Nbr: 23453
Date: 11/07/2008
Fee: $175
