



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
567199

EQUIPMENT INSPECTED

State Number: 23562 Type of Unit: Passenger Landings: 2 Manuf: THYSSEN KRUPP
Capacity: 2100 Installed: 05/24/2006 Complied: 10/12/2006 Speed: 95
Volts: 208 Floor to Floor: 1 to 2 Entrances: 1 Rope Size: 0
Owner: SEA COAST REALTY, 4911 LONGBEACH ROAD, SOUTH PORT, NC, 28461
Occupant: LIVE OAK BLDG SEA COAST REALTY, 4911 LONGBEACH ROAD, SOUTH PORT, NC, 28461

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County Name	County Code
11/20/2008	Routine	Re-issued	48 - Martin	BRUNSWICK	10

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

n/a No violations found

Violations pointed out to: CHLOE GRANT

Inspector _____

INVOICE

No other invoice will be issued.

If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: SEA COAST REALTY, 4911 LONGBEACH ROAD, SOUTH PORT, NC, 28461
Occupant: LIVE OAK BLDG SEA COAST REALTY, 4911 LONGBEACH ROAD, SOUTH
PORT, NC, 28461

Invoice Number
567199

State Nbr: 23562
Date: 11/20/2008
Fee: \$175