

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
567222

EQUIPMENT INSPECTED

State Number: H1353 Type of Unit: Hand Lift Landings: 2 Manuf: GARAVENTA
Capacity: 750 Installed: 02/27/2003 Complied: 02/27/2003 Speed: 12
Volts: 120 Floor to Floor: 1 to 2 Entrances: 2 Rope Size: 0
Owner: VICTORIA RAG PATCH, 10164 BEACH DRIVE SW, CALABASH, NC, 28468
Occupant: VICTORIA RAG PATCH, 10164 BEACH DRIVE SW, CALABASH, NC, 28468

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County Name	County Code
12/02/2008	Routine	Re-issued	48 - Martin	BRUNSWICK	10

Violation Abatement Date: 12/22/2008

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

8.6.1.6.3[e] Properly maintain all Control and operating circuits and devices. Unable to run unit in down dir. [repair].

Violations pointed out to: RANDY

Inspector _____

INVOICE

No other invoice will be issued.
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: VICTORIA RAG PATCH, 10164 BEACH DRIVE SW, CALABASH, NC, 28468
Occupant: VICTORIA RAG PATCH, 10164 BEACH DRIVE SW, CALABASH, NC, 28468

Invoice Number
567222
State Nbr: H1353
Date: 12/02/2008
Fee: \$65