

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm Invoice Number 567226

EQUIPMENT INSPECTED						
State Number: 11693 Capacity: 2000 Volts: 0 Owner: WEST BEACH VILLA, 271		Type of Unit: Installed: 02/ Floor to Floor VILLA, 2714 W BEACH	Type of Unit: Passenger Installed: 02/19/1987 Floor to Floor: G to 3 2714 W BEACH DRIVE, LONG BEACH, NA, 2714 W. BEACH DRIVE, LONG BEACH		Landings: 4 Complied: 02/19/1987 Entrances: 4 NC, 28461	
			INSPECTION INFO	PRMATION		
Inspection Date 12/03/2008		Type Inspection Routine	Certificate Status Re-issued		County Name BRUNSWICK	
Violatio	n Abatement	Date: 12/23/2008	VIOLATIONS FOU	ND		
	nto complianc	u in writing on Corrected Ve with current codes.  intain hangers, tracks, doo				
8.1.1[c]	Keys shall b	[TOP & BOTTOM].  be kept on the premises in a  to the general public.	location readily accessib	le to the personnel in	the assigned group, b	out not where they are
8.6.4.15		operation of signaling devi	ces,lighting, communicat	ion, and ventilation, sl	nall be maintained. E	Emer. Phone inoperative
Violations pointed out to: UNAVAILABLE				Inspector		
			INVOIC	E		
		No other invoice	will be issued	·		

No other invoice will be issued. If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division, 1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: WEST BEACH VILLA, 2714 W BEACH DRIVE, LONG BEACH, NC, 28461 Occupant: WEST BEACH VILLA, 2714 W. BEACH DRIVE, LONG BEACH, NC, 28461

Invoice Number 567226

State Nbr: 11693 Date: 12/03/2008 Fee: \$175