



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
567427

EQUIPMENT INSPECTED

State Number: 24471 Type of Unit: Passenger Landings: 2 Manuf: SCHINDLER, HYD
Capacity: 2100 Installed: 12/14/2006 Complied: Speed: 100
Volts: 208 Floor to Floor: 1 to 2 Entrances: 1 Rope Size: 0
Owner: SECURITY SAVINGS BANK, 5201 SOUTHPORT SUPPLY RD, SOUTHPORT, NC, 28465
Occupant: SECURITY SAVINGS BANK, 5201 SOUTHPORT SUPPLY RD, SOUTHPORT, NC, 28465

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County Name	County Code
03/17/2009	Routine	Re-issued	48 - Martin	BRUNSWICK	10

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

n/a No violations found

Violations pointed out to: PAT

Inspector _____

INVOICE

No other invoice will be issued.

If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: SECURITY SAVINGS BANK, 5201 SOUTHPORT SUPPLY RD, SOUTHPORT, NC,
28465
Occupant: SECURITY SAVINGS BANK, 5201 SOUTHPORT SUPPLY RD, SOUTHPORT, NC,
28465

Invoice Number
567427

State Nbr: 24471
Date: 03/17/2009
Fee: \$175