



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
575292

EQUIPMENT INSPECTED

State Number: 5813	Type of Unit: Freight	Landings: 2	Manuf: WESTBROOK
Capacity: 8000	Installed: 04/08/1968	Complied: 10/11/1991	Speed: 100
Volts: 550	Floor to Floor: 1 to 2	Entrances: 1	Rope Size:
Owner: CULP FABRICS INC, PO BOX 117, GRAHAM, NC, 27253			
Occupant: CULP FABRICS / WEAVING ROOM, 300 PARKER ST, GRAHAM, NC, 27253			

INSPECTION INFORMATION

Inspection Date 07/28/2008	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 36 - Kirkman	County Name ALAMANCE	County Code 1
-------------------------------	----------------------------------	----------------------------------	---------------------------	-------------------------	------------------

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

spoke with new owner, waiting for power to be turned on to building. Kevin will contact me for inspection when power is restored to the building!

Violations pointed out to: office

Inspector _____

INVOICE

No other invoice will be issued.
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: CULP FABRICS INC, PO BOX 117, GRAHAM, NC, 27253
Occupant: CULP FABRICS / WEAVING ROOM, 300 PARKER ST, GRAHAM, NC, 27253

Invoice Number
575292

State Nbr: 5813
Date: 07/28/2008
Fee: \$0