



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)

Invoice Number  
**575419**

### EQUIPMENT INSPECTED

State Number: 19412	Type of Unit: Passenger	Landings: 3	Manuf: THYSSEN KRUPP
Capacity: 2500	Installed: 08/01/2000	Complied: 08/01/2000	Speed: 100
Volts: 200	Floor to Floor: 1 to 3	Entrances: 1	Rope Size:
Owner: B.C. PARKER REAL ESTATE, 336-226-8411, BURLINGTON, NC, 27429			
Occupant: DELANEY CROSSING BLDG #1, 2221 DELANEY DR, BURLINGTON, NC, 27215			

### INSPECTION INFORMATION

Inspection Date 09/30/2008	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County Name ALAMANCE	County Code 1
-------------------------------	----------------------------	---------------------------------	---------------------------	-------------------------	------------------

### VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

No violations found

Violations pointed out to: OFFICE

Inspector \_\_\_\_\_

### INVOICE

No other invoice will be issued.  
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,  
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: B.C. PARKER REAL ESTATE, 336-226-8411, BURLINGTON, NC, 27429  
Occupant: DELANEY CROSSING BLDG #1, 2221 DELANEY DR, BURLINGTON, NC, 27215

Invoice Number  
**575419**  
State Nbr: 19412  
Date: 09/30/2008  
Fee: \$175