



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)

Invoice Number  
**575422**

### EQUIPMENT INSPECTED

State Number: 25205	Type of Unit: Passenger	Landings: 2	Manuf: OTIS
Capacity: 3500	Installed: 09/25/2007	Complied: 09/25/2007	Speed: 100
Volts: 208	Floor to Floor: 1 to 2	Entrances: 1	Rope Size:
Owner: JULIE BLUE WILLIAMS, P O BOX 1447, HILLSBOROUGH, NC, 27278			
Occupant: FIVE STAR BUILDING, 104 E CENTER STREET, MEBANE, NC, 27302			

### INSPECTION INFORMATION

Inspection Date 10/07/2008	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County Name ALAMANCE	County Code 1
-------------------------------	----------------------------	---------------------------------	---------------------------	-------------------------	------------------

### VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

No violations found

Violations pointed out to: office

Inspector \_\_\_\_\_

### INVOICE

No other invoice will be issued.  
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,  
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: JULIE BLUE WILLIAMS, P O BOX 1447, HILLSBOROUGH, NC, 27278  
Occupant: FIVE STAR BUILDING, 104 E CENTER STREET, MEBANE, NC, 27302

Invoice Number  
**575422**

State Nbr: 25205  
Date: 10/07/2008  
Fee: \$175