



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
575428

EQUIPMENT INSPECTED

State Number: 26097 Type of Unit: Passenger Landings: 3 Manuf: SCHINDLER
Capacity: 2500 Installed: 05/13/2008 Complied: 05/13/2008 Speed: 100
Volts: 208 Floor to Floor: 1 to 3 Entrances: 1 Rope Size:
Owner: ETHAN POINTE, 1176 KIRKPATRICK ROAD, BURLINGTON, NC, 27215
Occupant: ETHAN POINTE APTS BLDG 3, 1176 KIRKPATRICK RD, BURLINGTON, NC, 27215

Elevator Name: BUILDING # 3

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County Name	County Code
10/10/2008	Compliance	Prev Issued	36 - Kirkman	ALAMANCE	1

Violation Abatement Date: 11/09/2008

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

2.27.1.1.2	Put the in car emergency telephone in proper working order.
8.6.4.7.4	Remove the water from the pit floor.

Violations pointed out to: OFFICE

Inspector _____

INVOICE

No other invoice will be issued.

If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: ETHAN POINTE, 1176 KIRKPATRICK ROAD, BURLINGTON, NC, 27215
Occupant: ETHAN POINTE APTS BLDG 3, 1176 KIRKPATRICK RD, BURLINGTON, NC,
27215

Invoice Number
575428

State Nbr: 26097
Date: 10/10/2008
Fee: \$0