



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
575447

EQUIPMENT INSPECTED

State Number: 10552	Type of Unit: Passenger	Landings: 2	Manuf: THYSSEN KRUPP
Capacity: 2100	Installed: 05/23/1983	Complied: 05/23/1983	Speed: 100
Volts: 200	Floor to Floor: 1 to 2	Entrances: 1	Rope Size:
Owner: TWIN LAKE CENTER, 100 WADE COBLE DR, BURLINGTON, NC, 27215			
Occupant: TWIN LAKE CENTER, 100 WADE COBLE DR, BURLINGTON, NC, 27215			

INSPECTION INFORMATION

Inspection Date 11/03/2008	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County Name ALAMANCE	County Code 1
-------------------------------	----------------------------	---------------------------------	---------------------------	-------------------------	------------------

Violation Abatement Date: 12/03/2008

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

2.27.1.1.2 Put the in car emergency telephone in proper working order.

Violations pointed out to: OFFICE

Inspector _____

INVOICE

No other invoice will be issued.
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: TWIN LAKE CENTER, 100 WADE COBLE DR, BURLINGTON, NC, 27215
Occupant: TWIN LAKE CENTER, 100 WADE COBLE DR, BURLINGTON, NC, 27215

Invoice Number
575447

State Nbr: 10552
Date: 11/03/2008
Fee: \$175