



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)

Invoice Number  
**575475**

### EQUIPMENT INSPECTED

State Number: H1137      Type of Unit: Hand Lift      Landings: 2      Manuf: GARAVENTA  
Capacity: 750      Installed: 05/29/2001      Complied: 05/29/2001      Speed: 10  
Volts: 220      Floor to Floor: LL to UL      Entrances: 2      Rope Size:  
Owner: ALAMANCE BURLINGTON SCHOOLS, 1712 VAUGHN RD, BURLINGTON, NC, 27217  
Occupant: WILLIAMS HIGH SCHOOL, 1307 S CHURCH ST, BURLINGTON, NC, 27215

### INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County Name	County Code
11/18/2008	Routine	Re-issued	36 - Kirkman	ALAMANCE	1

### VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

No violations found

Violations pointed out to: office

Inspector \_\_\_\_\_

### INVOICE

No other invoice will be issued.

If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,  
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: ALAMANCE BURLINGTON SCHOOLS, 1712 VAUGHN RD, BURLINGTON, NC, 27217

Occupant: WILLIAMS HIGH SCHOOL, 1307 S CHURCH ST, BURLINGTON, NC, 27215

Invoice Number  
**575475**

State Nbr: H1137  
Date: 11/18/2008  
Fee: \$65