



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
575524

EQUIPMENT INSPECTED

State Number: 17863	Type of Unit: Passenger	Landings: 4	Manuf: THYSSEN KRUPP
Capacity: 4500	Installed: 10/01/1998	Complied: 10/01/1998	Speed: 110
Volts: 200	Floor to Floor: B to 2	Entrances: 2	Rope Size:
Owner: DAVIS ST METHODIST CHURCH, 606 E DAVIS ST, BURLINGTON, NC, 27215			
Occupant: DAVIS ST METHODIST CHURCH, 606 E DAVIS ST, BURLINGTON, NC, 27215			

INSPECTION INFORMATION

Inspection Date 12/05/2008	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County Name ALAMANCE	County Code 1
-------------------------------	----------------------------	---------------------------------	---------------------------	-------------------------	------------------

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

No violations found

Violations pointed out to: office

Inspector _____

INVOICE

No other invoice will be issued.
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: DAVIS ST METHODIST CHURCH, 606 E DAVIS ST, BURLINGTON, NC, 27215
Occupant: DAVIS ST METHODIST CHURCH, 606 E DAVIS ST, BURLINGTON, NC, 27215

Invoice Number
575524

State Nbr: 17863
Date: 12/05/2008
Fee: \$175