

N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)

Invoice Number  
**575529**

EQUIPMENT INSPECTED

State Number: 25796                      Type of Unit: Passenger                      Landings: 2                      Manuf: OTIS  
Capacity: 2500                      Installed:                      Complied:                      Speed: 100  
Volts: 208                      Floor to Floor: 1 to 2                      Entrances: 1                      Rope Size:  
Owner: CHAD PORTERFIELD, 2004A ANTHONY ROAD, BURLINGTON, NC, 27215  
Occupant: WOODBURY PARK, 2929 CROUSE LANE, BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County Name	County Code
12/23/2008	New	Issued	36 - Kirkman	ALAMANCE	1

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

THIS UNIT IS IN COMPLIANCE HIS DATE 12-23-2008

Violations pointed out to: Joe

Inspector \_\_\_\_\_

INVOICE

No other invoice will be issued.  
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,  
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: CHAD PORTERFIELD, 2004A ANTHONY ROAD, BURLINGTON, NC, 27215  
Occupant: WOODBURY PARK, 2929 CROUSE LANE, BURLINGTON, NC, 27215

Invoice Number  
**575529**  
State Nbr: 25796  
Date: 12/23/2008  
Fee: \$200