

N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
575529

EQUIPMENT INSPECTED

State Number: 25796 Type of Unit: Passenger Landings: 2 Manuf: OTIS
Capacity: 2500 Installed: Complied: Speed: 100
Volts: 208 Floor to Floor: 1 to 2 Entrances: 1 Rope Size:
Owner: CHAD PORTERFIELD, 2004A ANTHONY ROAD, BURLINGTON, NC, 27215
Occupant: WOODBURY PARK, 2929 CROUSE LANE, BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County Name	County Code
12/23/2008	New	Issued	36 - Kirkman	ALAMANCE	1

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

THIS UNIT IS IN COMPLIANCE HIS DATE 12-23-2008

Violations pointed out to: Joe

Inspector _____

INVOICE

No other invoice will be issued.
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: CHAD PORTERFIELD, 2004A ANTHONY ROAD, BURLINGTON, NC, 27215
Occupant: WOODBURY PARK, 2929 CROUSE LANE, BURLINGTON, NC, 27215

Invoice Number
575529
State Nbr: 25796
Date: 12/23/2008
Fee: \$200