



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)

Invoice Number  
**575529**

### EQUIPMENT INSPECTED

State Number: 25796	Type of Unit: Passenger	Landings: 2	Manuf: OTIS
Capacity: 2500	Installed:	Complied:	Speed: 100
Volts: 208	Floor to Floor: 1 to 2	Entrances: 1	Rope Size:
Owner: CHAD PORTERFIELD, 2004A ANTHONY ROAD, BURLINGTON, NC, 27215			
Occupant: WOODBURY PARK, 2929 CROUSE LANE, BURLINGTON, NC, 27215			

### INSPECTION INFORMATION

Inspection Date 12/23/2008	Type Inspection New	Certificate Status Issued	Inspector 36 - Kirkman	County Name ALAMANCE	County Code 1
-------------------------------	------------------------	------------------------------	---------------------------	-------------------------	------------------

### VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

THIS UNIT IS IN COMPLIANCE HIS DATE 12-23-2008

Violations pointed out to: Joe

Inspector \_\_\_\_\_

### INVOICE

No other invoice will be issued.  
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,  
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: CHAD PORTERFIELD, 2004A ANTHONY ROAD, BURLINGTON, NC, 27215  
Occupant: WOODBURY PARK, 2929 CROUSE LANE, BURLINGTON, NC, 27215

Invoice Number  
**575529**

State Nbr: 25796  
Date: 12/23/2008  
Fee: \$200