



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)

Invoice Number  
**575568**

### EQUIPMENT INSPECTED

State Number: 2031	Type of Unit: Passenger	Landings: 7	Manuf: SOUTHERN
Capacity: 2500	Installed: 09/22/1983	Complied: 08/25/2005	Speed: 200
Volts: 200	Floor to Floor: 1 to 7	Entrances: 1	Rope Size: 1/2
Owner: BEACON MANAGEMENT, PO BOX 29229, GREENSBORO, NC, 27429-9229			
Occupant: ALAMANCE PLAZA, 111 MAPLE AVE, BURLINGTON, NC, 27215			

### INSPECTION INFORMATION

Inspection Date 01/13/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County Name ALAMANCE	County Code 1
-------------------------------	----------------------------	---------------------------------	---------------------------	-------------------------	------------------

### VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

No violations found

Violations pointed out to: office

Inspector \_\_\_\_\_

### INVOICE

No other invoice will be issued.  
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,  
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: BEACON MANAGEMENT, PO BOX 29229, GREENSBORO, NC, 27429-9229  
Occupant: ALAMANCE PLAZA, 111 MAPLE AVE, BURLINGTON, NC, 27215

Invoice Number  
**575568**  
State Nbr: 2031  
Date: 01/13/2009  
Fee: \$200