



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
575596

EQUIPMENT INSPECTED

State Number: 6017 Type of Unit: Passenger Landings: 2 Manuf: THYSSEN KRUPP
Capacity: 3000 Installed: 09/10/1968 Complied: 09/10/1968 Speed: 100
Volts: 460 Floor to Floor: 1 to 2 Entrances: 1 Rope Size:
Owner: CITY OF BURLINGTON, PO BOX 1358, BURLINGTON, NC, 27216
Occupant: MUNICIPAL BUILDING, 425 S LEXINGTON AVE, BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County Name	County Code
01/23/2009	Routine	Re-issued	36 - Kirkman	ALAMANCE	1

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

No violations found

Violations pointed out to: office

Inspector _____

INVOICE

No other invoice will be issued.
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: CITY OF BURLINGTON, PO BOX 1358, BURLINGTON, NC, 27216
Occupant: MUNICIPAL BUILDING, 425 S LEXINGTON AVE, BURLINGTON, NC, 27215

Invoice Number
575596
State Nbr: 6017
Date: 01/23/2009
Fee: \$175