



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
575608

EQUIPMENT INSPECTED

State Number: 9974	Type of Unit: Passenger	Landings: 2	Manuf: THYSSEN KRUPP
Capacity: 4000	Installed: 11/10/1981	Complied: 11/10/1981	Speed: 125
Volts: 480	Floor to Floor: 1 to 2	Entrances: 1	Rope Size:
Owner: MEDTOX DIAGNOSTICS, INC, 1238 ANTHONY RD, BURLINGTON, NC, 27215			
Occupant: MEDTOX DIAGNOSTICS, INC, 1238 ANTHONY RD, BURLINGTON, NC, 27215			

INSPECTION INFORMATION

Inspection Date 02/02/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County Name ALAMANCE	County Code 1
-------------------------------	----------------------------	---------------------------------	---------------------------	-------------------------	------------------

Violation Abatement Date: 03/04/2009

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

- 8.6.5.7 Provide an oil usage log in the machine room recording the quantity of hydraulic fluid added to the system and emptied from leakage catch pan and containers.
- 8.11.2.2.2 Perform the annual no load safety test

Violations pointed out to: OFFICE

Inspector _____

INVOICE

No other invoice will be issued.
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: MEDTOX DIAGNOSTICS, INC, 1238 ANTHONY RD, BURLINGTON, NC, 27215
Occupant: MEDTOX DIAGNOSTICS, INC, 1238 ANTHONY RD, BURLINGTON, NC, 27215

Invoice Number
575608
State Nbr: 9974
Date: 02/02/2009
Fee: \$175