



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
575611

EQUIPMENT INSPECTED

State Number: 6260	Type of Unit: Passenger	Landings: 2	Manuf: SOUTHERN
Capacity: 2000	Installed: 01/13/1969	Complied: 05/07/1996	Speed: 75
Volts: 220	Floor to Floor: 1 to 2	Entrances: 1	Rope Size:
Owner: CAROLINA BIO SUPPLY, 2700 YORK RD, BURLINGTON, NC, 27215			
Occupant: CAROLINA BIO SUPPLY, 2700 YORK RD, BURLINGTON, NC, 27215			

INSPECTION INFORMATION

Inspection Date 02/03/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County Name ALAMANCE	County Code 1
-------------------------------	----------------------------	---------------------------------	---------------------------	-------------------------	------------------

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

No violations found

Violations pointed out to: office

Inspector _____

INVOICE

No other invoice will be issued.
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: CAROLINA BIO SUPPLY, 2700 YORK RD, BURLINGTON, NC, 27215
Occupant: CAROLINA BIO SUPPLY, 2700 YORK RD, BURLINGTON, NC, 27215

Invoice Number
575611

State Nbr: 6260
Date: 02/03/2009
Fee: \$175