



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)

Invoice Number  
**575622**

EQUIPMENT INSPECTED

State Number: 21988	Type of Unit: Passenger	Landings: 2	Manuf: THYSSEN KRUPP
Capacity: 2100	Installed: 10/16/2003	Complied: 10/16/2003	Speed: 80
Volts: 208	Floor to Floor: 1 to 2	Entrances: 1	Rope Size: 0
Owner: MEBANE POLICE STATION, 116 W CENTER STREET, MEBANE, NC, 27302			
Occupant: MEBANE POLICE STATION, 116 W CENTER STREET, MEBANE, NC, 27302			

INSPECTION INFORMATION

Inspection Date 02/12/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County Name ALAMANCE	County Code 1
-------------------------------	----------------------------	---------------------------------	---------------------------	-------------------------	------------------

Violation Abatement Date: 03/14/2009

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

2.14.7.1.3 Put the in car emergency light in working order.

Violations pointed out to: OFFICE

Inspector \_\_\_\_\_

INVOICE

No other invoice will be issued.  
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,  
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: MEBANE POLICE STATION, 116 W CENTER STREET, MEBANE, NC, 27302  
Occupant: MEBANE POLICE STATION, 116 W CENTER STREET, MEBANE, NC, 27302

Invoice Number  
**575622**

State Nbr: 21988  
Date: 02/12/2009  
Fee: \$175