



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
575647

EQUIPMENT INSPECTED

State Number: 4698	Type of Unit: Freight	Landings: 2	Manuf: SOUTHERN
Capacity: 7500	Installed: 10/01/1962	Complied: 04/08/2004	Speed: 60
Volts: 550	Floor to Floor: 1 to 2	Entrances: 1	Rope Size: 0
Owner: CAROLINA FINISHING OF NC, PO BOX 2226, BURLINGTON, NC, 27216			
Occupant: CAROLINA FINISHING OF NC LLC, 220 ELMIRA ST, BURLINGTON, NC, 27217			

INSPECTION INFORMATION

Inspection Date 02/18/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County Name ALAMANCE	County Code 1
-------------------------------	----------------------------	---------------------------------	---------------------------	-------------------------	------------------

Violation Abatement Date: 03/20/2009

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

8.11.2.2.2	Perform the annual no load safety test. (SECOND NOTICE 30 DAYS)
8.6.4.7.1	Clean the elevator pit.

Violations pointed out to: OFFICE

Inspector _____

INVOICE

No other invoice will be issued.
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: CAROLINA FINISHING OF NC, PO BOX 2226, BURLINGTON, NC, 27216
Occupant: CAROLINA FINISHING OF NC LLC, 220 ELMIRA ST, BURLINGTON, NC, 27217

Invoice Number
575647

State Nbr: 4698
Date: 02/18/2009
Fee: \$175