



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
575657

EQUIPMENT INSPECTED

State Number: 15191	Type of Unit: Passenger	Landings: 3	Manuf: USEC
Capacity: 2500	Installed: 02/09/1994	Complied: 02/09/1994	Speed: 115
Volts: 240	Floor to Floor: 1 to 3	Entrances: 1	Rope Size:
Owner: GLEN HOPE BAPTIST CHURCH, 911 NORTH AVE, BURLINGTON, NC, 27217			
Occupant: GLEN HOPE BAPTIST CHURCH, 911 NORTH AVE, BURLINGTON, NC, 27217			

INSPECTION INFORMATION

Inspection Date 02/23/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County Name ALAMANCE	County Code 1
-------------------------------	----------------------------	---------------------------------	---------------------------	-------------------------	------------------

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

No violations found

Violations pointed out to: OFFICE

Inspector _____

INVOICE

No other invoice will be issued.
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: GLEN HOPE BAPTIST CHURCH, 911 NORTH AVE, BURLINGTON, NC, 27217
Occupant: GLEN HOPE BAPTIST CHURCH, 911 NORTH AVE, BURLINGTON, NC, 27217

Invoice Number
575657

State Nbr: 15191
Date: 02/23/2009
Fee: \$175