

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm

Invoice Number **575667**

		w w w.nciabor.cc					
		EQUIPMENT I	NSPECTED				
State Number: 15427 Type of Unit: Passenger Capacity: 2100 Installed: 10/11/1994 Volts: 208 Floor to Floor: 1 to 2 Owner: ALAMANCE - BURLINGTON SCHOOL SYSTE Occupant: TURRENTINE MIDDLE SCHOOL, 1710 EDG		994 Com o 2 Entra o SYSTEM, 1712 VAU					
		INSPECTION IN	FORMATION				
Inspection Date 02/26/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County Name ALAMANCE	County Code		
		VIOLATIONS	S FOUND				
Notify the Elevator B	ureau in writing on Correct equ	ted Violations Form what into compliant		ons have been made in	order to bring you		
No violations found							
				_			
Violations pointed out to: office			Inspector				
		INVO	ICE				
If not noid with	No other invoice		aggamag invalid				
If not paid within 30 days from date of invoice, your certi Return this stub with payment to: NC Department of Labor, Budget 1101 Mail Service Center, Raleigh, NC 27699-1101				Invoice Number 575667			
Owner: ALAMANCE - BURLINGTON SCHOOL SYSTEM, 1712 VABURLINGTON, NC, 27217 Occupant: TURRENTINE MIDDLE SCHOOL, 1710 EDGEWOOD AV				Date:			
Occupant: TURRENTIN 27215	ie middle school, 17	IU EDGEWOOD AVE	s, BURLINGTON, NC,				