

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm

Invoice Number 575668

		EQUIPMENT IN	SPECTED			
State Number: H823 Type of Unit: Hand Lift Capacity: 550 Installed: 01/12/1998 Volts: 110 Floor to Floor: LL to UL Owner: ALAMANCE - BURLINGTON SCHOOL SYSTEM, 12 Occupant: TURRENTINE MIDDLE SCHOOL, 1710 EDGEWO		1998 Cor LL to UL Ent L SYSTEM, 1227 VAUC		Speed: 9 Rope Size: N, NC, 27217	Rope Size: C, 27217	
INSPECTION INFORMATION						
Inspection Date 02/26/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County Name ALAMANCE	County Code	
		VIOLATIONS	FOUND			
Notify the Elevator B	ureau in writing on Correct	cted Violations Form whe		ons have been made in	order to bring you	
No violations found						
$ar{y}$ iolations pointed out to:	office			Inspector		
		INVOIC				
Return this stub with pay 1101 Mail Service Cente Owner: ALAMANCE - BURLINGTON, NC, 27	No other invoice nin 30 days from date of in ment to: NC Department r, Raleigh, NC 27699-110 BURLINGTON SCHOO 217 E MIDDLE SCHOOL, 1	nvoice, your certificate be of Labor, Budget and Pur ol ol SYSTEM, 1227 VAUC	chasing Division, GHN RD,	575 State Nbr: Date:	e Number 5668 H823 02/26/2009 \$65	