



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
575680

EQUIPMENT INSPECTED

State Number: 23117 Type of Unit: Passenger Landings: 3 Manuf: SCHINDLER
Capacity: 2100 Installed: 11/28/2005 Complied: 12/27/2005 Speed: 125
Volts: 208 Floor to Floor: 1 to 3 Entrances: 1 Rope Size: .
Owner: HAROLD K JORDAN, 1806 CLASIC RD, APEX, NC, 27532
Occupant: RIVER MILL, 1613 BETHLEHAM CHRUCH RD, SAXAPAHAW, NC, 27340

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County Name	County Code
03/06/2009	Routine	Re-issued	36 - Kirkman	ALAMANCE	1

Violation Abatement Date: 04/05/2009

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

8.6.4.7.4 Remove the oil from the pit floor.

Violations pointed out to: office

Inspector _____

INVOICE

No other invoice will be issued.
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: HAROLD K JORDAN, 1806 CLASIC RD, APEX, NC, 27532
Occupant: RIVER MILL, 1613 BETHLEHAM CHRUCH RD, SAXAPAHAW, NC, 27340

Invoice Number
575680
State Nbr: 23117
Date: 03/06/2009
Fee: \$175