

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm

Invoice Number 575684

		EQUIPMENT INS	PECTED		
Occupant: FIRST PRES	acity: 2100 Installed:		DAVIS STREET, BURLINGTON, NC, 27215		eed: 80 pe Size: 5 215
		INSPECTION INFO	RMATION		
Inspection Date 03/09/2009	Type Inspection New	Certificate Status	Inspector 36 - Kirkman	County Name	
		VIOLATIONS F	OUND		
•		ted Violations Form when uipment into compliance v		ns have been made is	n order to bring your
Violations pointed out to: chris		Inspector			
		INVOICE			
Return this stub with pay 1101 Mail Service Center	rment to: NC Department or, Raleigh, NC 27699-110	voice, your certificate become f Labor, Budget and Purcle	nasing Division,	11	ce Number 75684 26563 03/09/2009 \$200

Occupant: FIRST PRESBYTERIAN CHURCH OF BURLINGTON, 508 W DAVIS STREET,

BURLINGTON, NC, 27215