



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)

Invoice Number  
**575717**

### EQUIPMENT INSPECTED

State Number: H42	Type of Unit: Hand Lift	Landings: 2	Manuf: WECO
Capacity: 300	Installed: 12/11/1980	Complied: 12/11/1980	Speed: 25
Volts: 110	Floor to Floor: UL to LL	Entrances: 1	Rope Size:
Owner: EBENEZER UNITED CHURCH, 734 APPLE ST, BURLINGTON, NC, 27215			
Occupant: EBENEZER UNITED CHURCH, 734 APPLE ST, BURLINGTON, NC, 27215			

### INSPECTION INFORMATION

Inspection Date 04/06/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County Name ALAMANCE	County Code 1
-------------------------------	----------------------------	---------------------------------	---------------------------	-------------------------	------------------

### VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

No violations found

Violations pointed out to: office

Inspector \_\_\_\_\_

### INVOICE

No other invoice will be issued.  
If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,  
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: EBENEZER UNITED CHURCH, 734 APPLE ST, BURLINGTON, NC, 27215  
Occupant: EBENEZER UNITED CHURCH, 734 APPLE ST, BURLINGTON, NC, 27215

Invoice Number  
**575717**  
State Nbr: H42  
Date: 04/06/2009  
Fee: \$65