



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm

Invoice Number
581403

EQUIPMENT INSPECTED

State Number: H1027 Type of Unit: Hand Lift Landings: 2 Manuf: GARAVENTA
Capacity: 495 Installed: 02/01/2000 Complied: 02/21/2000 Speed: 20
Volts: 220 Floor to Floor: 1 to 2 Entrances: 2 Rope Size: 8mm
Owner: ASHE CO SCHOOLS, PO BOX 604, JEFFERSON, NC, 28640
Occupant: ASHE CO MIDDLE SCHOOL, 255 NORTHWEST DR, WARRENSVILLE, NC, 28693

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County Name	County Code
07/31/2008	Routine	Re-issued	7 - Hoffman	ASHE	5

Violation Abatement Date: 08/30/2008

VIOLATIONS FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

8.6 CLEAN AND PROPERLY MAINTAIN THE LIFT

Violations pointed out to: ASHE CO. BOARD OF ED. 336-246-7175

Inspector _____

INVOICE

No other invoice will be issued.

If not paid within 30 days from date of invoice, your certificate becomes invalid.

Return this stub with payment to: NC Department of Labor, Budget and Purchasing Division,
1101 Mail Service Center, Raleigh, NC 27699-1101

Owner: ASHE CO SCHOOLS, PO BOX 604, JEFFERSON, NC, 28640
Occupant: ASHE CO MIDDLE SCHOOL, 255 NORTHWEST DR, WARRENSVILLE, NC,
28693

Invoice Number
581403

State Nbr: H1027
Date: 07/31/2008
Fee: \$65